: BASKET BASE ASSEMBLY (350)

Date User:

Monday, 22/12/2008 12:58:30 PM

Linda Lacelle

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number**

: 44227C

P.O. Number

: 10189

This Issue

: 22/12/2008

: NC

: //

: 43142A

: LARGE FAB ASSY Туре

Part Number

Drawing Name

: D2221

Drawing Number

. D2221 REVG

Project Number

Drawing Revision

Material

Due Date

: G : 29/12/2008

Qty:

1 Um: Each

Written By

Prsht Rev.

First Issue

Checked & Approved By Comment

Previous Run

: Est Rev:J 05.09.02

S.O. No. :

Added D3442-1

KJ/JLM

Est Rev:K 08-08-29 revG as per dwg DD verified by:EC Est Rev:L 08-09-24 plug holes prior to powder coat DD verified

by:EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

D31661

Basket Hoop

Comment: Qty.:

4.0000 Each(s)/Unit

Total:

4.0000 Each(s)

Pick:

Qty Part Number

Description

D3166-1

2.0

D22323

Basket Hinge



Comment: Qty.:

2.0000 Each(s)/Unit

Total:

2.0000 Each(s)



Qty Part Number

Description Batch

2 D2232-3 Hinge bracket \$\int 39334



D2325

3.0

Support Gusset (350 Basket)



Pick:

Total:

4.0000 Each(s)

Qty Part Number

Description

Support Gusset

4 D2325

Date: Monday, 22/12/2008 12:58:30 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: BASKET BASE ASSEMBLY (350) Job Number: 44227C Part Number: D2221 Job Number: Seq. #: Machine Or Operation: Description: 4.0 D23273 Spacer Bushing Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description B39560 2 D2327-3 Bushing 5.0 D2581 Mounting Bracket Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description Batch Mounting Bracket <u>B408</u>95 2 D2581 D34421 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description Batch B40392 2 D3442-1 Shim 7.0 M304EX07516F Expanded Metal Flat SS Comment: Qty.: 41.6745 sf(s)/Unit Total: 41.6745 sf(s) Pick: 10-8474 (4) Qty Part Number Description Batch 39.69 sf M304EX0.75-16F Expanded Metal 8.0 M304TS0750W065 304 SQ Tube .75x.75x.065W Comment: Qty.: 29.4000 f(s)/Unit Total: 29.4000 f(s) Pick: 3/4" x 3/4" x 0.065 wall 304/316 SStubing Batch: 71/(001) 08-12-22 SAD

Date: Monday, 22/12/2008 12:58:30 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: BASKET BASE ASSEMBLY (350) Job Number: 44227C Part Number: D2221 Job Number: Seq. #: Machine Or Operation: Description: LARGE FAB 1 9.0 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1-Cut D2235-1 Rib from D3166-1 Rib As Per Dwg D2235 2-Drill hole in D2221-3 as per Dwg D2221 3-Deburr 4-Remove all markings on material before welding 5-Weld as per Dwg D2221 using Welding Table and corner JigDeburr as required 10.0 QC9 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION 11.0 QC6 **DIMENSIONAL CHECK** Comment: DIMENSIONAL CHECK 12.0 POWDER COATING POWDER COATING m109996 Comment: POWDER COATING 1- Plug holes in D2581 prior to powder coating 2-Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 1ST COAT: START TIME: **OVEN TEMPERATURE:** FINISH TIME: ******************** 2nd coat if necessar FL 08/01/05 2ND COAT: START TIME: **OVEN TEMPERATURE:**

FINISH TIME:

Date:

Monday, 22/12/2008 12:58:30 PM

User:

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BASKET BASE ASSEMBLY (350)

Job Number: 44227C

Part Number: D2221

Job Number:



Seq. #:

Machine Or Operation:

Description:

13.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

14.0

QC21

FINAL INSPECTION/W/O RELEASE




Comment: FINAL INSPECTION/W/O RELEASE

Job Completion




D09/01/07


mf 09-01-0



-Dart Aerospace Ltd **WORK ORDER CHANGES** W/O: Approval **Approval** PROCEDURE CHANGE DATE STEP By Qtv Chief Eng / Prod Mgr Date QC Inspector Part No: ______ PAR #: ____ Fault Category: _____ NCR: Yes No DQA: ____ Date: ____ Disposition: QA: N/C Closed: Date: _____ Resolution: WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B **Description of NC** Verification **Approval** Approval DATE STEP Sign & **Action Description** Initial QC Inspector Section A Section C Chief Eng Date Chief Eng Chief Eng




	rospace Lt	<u>u</u>								
W/O:				WC	RK ORDER CHANG	GES				
DATE	STEP		PROCEDURE CHANGE			Ву	Date Qt	Approval Chief Eng / Prod Mgr	Approva QC Inspector	
		!								
		<u> </u>								
		!		1						
Part No):	<u> </u>	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:	 Date: _		
				\		QA: N/C Closed: Date:				
NCR:		1		WORK ORD	ER NON-CONFORM	ANCE (NC	R)			
DATE	OTED	Description of NC				tion B	Verificatio	n Approvai	Approval	
DATE	STEP		tion A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Section C	Chief Eng	QC Inspecto	
				, i		ŀ	!	1	ł	
						:				




Dart	Aer	ospa	ce	Ltd
------	-----	------	----	-----

,W/O:	-	·····		1	WORK ORDER CHANG	GES						
DATE	STEP		PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
			1	ļ	•							
			i 1	ļ					į			
, , ₁ , ₂ , ₂ , ₂				!								
			!									
Part No:			PAR #:	Fault Ca	ategory:	NCR	:Yes N	lo DQ /	A :	Date:		
	Res	solution:		Disposi	Disposition: C			QA: N/C Closed: Date:				
NCR:				WORK OR	DER NON-CONFORM	IANCE	(NCR)					
DATE	STEP	STEP Description of No Section A	tion of NC		Corrective Action Section B		Sign & Verification				Approval	
	SILF		ection A	Initial Chief Eng	Action Description Chief Eng		Date	Section C		Chief Eng	QC Inspector	
			İ	1	•						:	
			<u> </u> 									
			' 								<u> </u>	
					<u> </u>							
	1	!										



Dart Aerospac	e Ltd
---------------	-------

	•			1							
W/O:	W/O:				WORK ORDER O	CHANGES					
DATE	STEP		PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•							
			i	1							
			!	ĺ							
				i							
Part No:		PAR #:	Fault Category: N			NCR: Yes No DQA: Date:					
	R	esolution:	i	Disposition: C			A: N/C Closed: Date:				
NCR:			!	WORK O	RDER NON-CON	FORMANCE	(NCR)			
DATE	STED	STEP Descrip	Description of NC		Corrective Action Section B		Verification		Approval	Approval	
DAIL	SIEP		Section A	Initial Chief En		cription 19	Sign & Date	Section C		Chief Eng	QC Inspector
			1								
			1								
				1 1							
				i							·
			 					į			
				. 1							
		1								i	
				i							



D	Aeros	

	•											
,W/O:			.	V	VORK ORDER CHANG	ES		,				
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
		,										
			#P-140									
			; 									
Part No:			PAR #:	Fault Ca	tegory:	_ NCR: Yes	No DG	A:	Date:			
	R	esolution:			Disposition: Q							
NCR:			` 	WORK OR	DER NON-CONFORMA	ANCE (NC	R)			· *.		
DATE	STEP		ion of NC		Corrective Action Section B		Verification		Approval Chief Eng	Approval QC Inspector		
		Section A		Initial Chief Eng	Action Description Chief Eng			tion C				
				: - -								
			!									
				į.								
		,										
			1	1								